

Approved For Release 2007/01/17 : CIA-RDP74B00496R000400050086-6

SECRET

(When Filled In)

PRIORITY

FILE INFO

REPRODUCTION PROHIBITED

10 DEC 71 17 02 DM	1	6	DOPS	11	16
	2	7	INTEL	12	17
	3	8	HASC	13	18
DSA	4	9	IDEA	14	19
RB	5	10	"	15	20

SECRET 100540Z DEC 71 CITE 3490

PRIORITY

IDEALIST DM-1/4

REF: CARD 3437

SUBJ: MISSION C-361-C O/S

1. FURTHER INVESTIGATION OF O/S ACTIVATION SUGGESTS THERE WERE TWO (2) SEPARATE PROBLEMS DURING THE MISSION, EACH UNRELATED.

A. O/S ACTIVATIONS WERE PROBABLY CAUSED BY THE HF SSB

B. SYSTEM 17B L/W NOISE WAS CAUSED BY "H" CONFIG HEATERS. THIS IS SUBJECT OF A SEPARATE MESSAGE.

2. O/S PROBLEM CANNOT BE DUPLICATED ON THE GROUND. ALL ASSOCIATED EQUIPMENT HAS BEEN BENCH CHECKED AND REINSTALLED IN ARTICLE 053 FOR TESTING ON MONDAY 13 DEC 71. WILL REPORT RESULTS.

SECRET

BT